BellaVita at Green Tee							
2010 Scenario #24 Final Reser							
Annual Expenses by Year, Cur	rent Dollars						
				0040	0011	0010	0040
Year Year #	Engineers	2008 study	2010 study	2010 1	2011	2012	2013
	Lingineers	2000 Sludy	2010 Study	1	2	5	4
# homes for expenses				542	578	600	620
# homes for painting based on	schedule of closin	gs, 9 year for sec	ond paint	68	49	69	81
Linear ft for common iron							948
Linear ft for common wood Linear ft for unit iron							240 1873
Linear ft for unit wood							6163
Site							
Retention Pond	\$4,000 every 20 vr	\$4,000 every 20 yr	\$4,000 every 20yr				
Sidewalk repair	\$20,691 every 10 yr, 10% of total replace costs of \$206,910	\$5,000 every 2 yr, equal to 25,000 over 10 yr	\$5,000 every 2 yr, equal to 25,000 over 10 yr		10,000		5,000
	\$346,000 every 10 yr, 10% of total replace costs of	\$100,000 every	\$100,000 every 5 years, split in half		10,000	50.000	i
Private street repair	\$3,460,000 \$15,000 every 4 yr, 10% of total	5 years				50,000	50,000
Concrete curb repairs	replace costs of \$150,000	\$6,000 every 3 yr	\$6,000 every 3 yr			6,000	
River pumps	not in engineer	not in study	\$8,000 every 8 years				
			put in operating				
Entry gate paint	\$200 every 5 yr \$2,000 every 20	budget	budget 5,700 every 8				
	yr, 2 gates,	\$5,000 every 8	yr, Rusty cost				
Entry gates replace/modify	\$1,000 each	yr	of 2,850 each				5,700
Entry gate motor replacement	\$6,000 every 10 yr, 4 motor 1,500 each	\$6,000 every 10 yr	1 now then every 5 yrs based on warranty and 3,250 each		3,250		
Entry gate control computer replace	\$16,000 every 7 yr	\$16,000 every 7 yr	Rusty says 12,000 every 2 yr based on warranty. Used every 5 yr 948 linear ft @	30,070			
Wrought iron paint common	\$60,000 every 5 yr	combined below	\$2 every 5 years until replaced			1,896	
Wrought iron fencing replace common	\$150,000 every 5 yr, 25% of tota replacemnt cost of \$600,000	\$35,000 every 3 yr	\$23 foot @ 12 year, then 20 year		-	-	21,804
Wood fence replace (common)	\$45,000 every 10 yr, 6,000 ft at 7.5 ft	7.5 ft	year		-	-	4,080
	\$4,000 every 8	\$4,000 every 8	\$40,000 every				
Laba Farmet 1	yr, 4 at 1,000	yr, 4 at 1,000	10 yr, 4 at			00.000	00.000
Lake Fountain repair	each	each	10,000 each			20,000	20,000
Irrigation system repair	\$56,000 every 20 yr	\$3,000 every 3 yr	\$3,000 every 3 yr		3,000		
Residential sprinkler controls replace \$100 home 1/20 of h/স/2021 1	\$22,500 every 8 yr, 450 homes at \$50		10 yr life, 1/10 home total at \$75 each		3,000	4,500	4,650
	ψυυ	ψ100 Ga011			5,000	-,500	-,050

BellaVita at Green Tee							
2010 Scenario #24 Final Rese							
Annual Expenses by Year, Cu	rrent Dollars						
Year				2010	2011	2012	2013
Year #	Engineers	2008 study	2010 study	1	2	3	4
	\$1,800 every 20	\$5,000 every 4	\$5,000 every 4			F 000	
Monument & bell tower repair	yr	yr	yr ¢18.200everv			5,000	
			\$18,200every 21 yr split by				
			4=5,000 every				
	\$42,750 every		5 year, 10% of				
	21 yr, 10% of		total replace				
	total replace	\$5,000 every 5,	cost of				
	cost of 427,500	or 20,000 every	\$182,000				
Contrete wall repair	(2,850 @ 150)	20 yr	(3,500 @ \$52)			5,000	
	\$2,000 every 15		\$6,000 (1,000				
Clubhouse parking lights	yr, 8 lights at		per 6 lights)				
replace	\$250	not in study	every 5 years			6,000	
	\$19,560 every						
	11 yr, 10% of	\$5,000 every 5	\$5,000 every 5				
Clubhouse pavement repair	cost of 195,600.	\$5,000 every 5	\$5,000 every 5 yr			5,000	
	\$8,600 every 5	<i>J</i> .	<i>j</i> .			0,000	
	yr, 20% of total						
	replace cost of	\$2,500 every 5	\$2,500 every 5				
Brick paver repairs	43,000	yr	yr			2,500	
Structure							
Exterior Systems	<b>A0</b> 100 <b>F</b>	<b>*</b> 45.000	<b>#</b> 45.000				
Clubhouse, monument sign, tower & guardhouse painting	\$9,400 every 5 vr	\$15,000 every 5 yr	\$15,000 every 10 yr	2,290			
tower & guardhouse painting	уг	буг	Cost to	2,290			
			replace				
	\$22,842 every		150,000 in 30-				
	50 yr 50% of	none in study,	40 yr not study				
Clubhouse roof replace	45,600 total cost		term				
			Quote of \$7				
			per ft 256 ft				
	<b>#</b> 4.000 45	<b>.</b>	\$1792, life at				
Clubbauga guttara raplaga	\$1,280 every 15	\$4,000 every 15 yr	least 15 leave				
Clubhouse gutters replace	yr 256 lf @5 \$28,125 each yr	15 yi	at \$4,000				
	half of 450	1/3 of homes	1/3 of homes				
Residential door painting	homes @ 125	@160	@160	6,495	26,250	32,000	33.067
						,	,
			\$1,500 per				
			schedule after				
			contract 8 year				
			life, increase to				
			9 years for study, but				
			evaluate and				
Residential house painting	\$112,500 1/8 of	\$1,500 per	repaint at 10				
\$1500 per 5 years schedule	450 homes at	schedule after	years if				
homes	2,000	contract	possible				121,500
			\$23 per linear				
			foot at 12 year,				
			then 20 year				
Unit iron fences replace	not in engineer		life		-	-	43,079
			9587 @ 2				
Unit iron fences paint	see above		every 5 year until replace			19,174	
orme non tonoeo paint			\$17 per linear			13,174	
			foot at 12 year,				
		\$500 per home	then 15 year				
Unit wood fences replace	not in engineer	1/10 of homes	life		-	-	104,771
Mechanical Systems							
			100 533	T		T	
	<b>*</b> 50.500	<b>#F0 F0 C</b>	162,500 every				
Air conditioning systems	\$58,500 every	\$58,500 every 10 yr, 13 unit at	10 yr, 13 unit at				
Air conditioning systems replace	10 yr, 13 unit at 4,500	4,500	9,000, phase over 4 years		25,000	50,000	50,000
1/7/2011	1,000	1,000	Svoi + yodis		20,000	50,000	50,000

BellaVita at Green Tee							
2010 Scenario #24 Final Reser Annual Expenses by Year, Cur							
Annual Expenses by Year, Cur							
Year				2010	2011	2012	2013
Year #	Engineers	2008 study	2010 study	1	2	3	4
Electric water heater replace Miscellaneous Amenities	\$800 every 12 yr	\$1,000 every 12 yr	2 heaters @ 1,000 each, \$2,000 every 10 yr		2,000		
Exercise equipment replacement	52,600 every 12 yr for all types of exercise equipment	\$6,000 every 3 yr	\$5,000 every 3 yr split		2,500	2,500	
			\$13,000 13 @				
Pool equipment-replace pumps	\$6,000 every 20 yr, 3 at 2,000	\$10,000 every 10 yr	1,000 every 5 yr (split up 3- 2,000 a year)		3,000	3,000	3,000
Pool equipment-replace filters Pool equipment-replace water heaters	\$450 every 8 yrs 3 at 150 \$21,000 every 10 yr, 6 at 3,500	operating budget \$21,000 every 10 yr 6 at 3,500	Bill Cole 12,000 every 10 yr 6 at 2,000 4 @ 3500 each, every 8 years		12,000		
	included with	included with	3500 every 2				
Spa equipment-replace heater	pool heaters	pool heaters	years		3,500		3,500
Swimming pool & spa re-	\$29,025 every	\$30,000 every	\$40,000 every				
plaster	15 yr	10 yr	10 yr			40,000	
			\$20,000 every				
pool deck	not in engineer \$25,000 every	not in study	10 yr			20,000	
Clubhouse carpet replace	10 yr for carpet, tile and appliance	\$20,000 every 10 yr	\$20,000 every 10 yr split		10,000	10,000	
Clubhouse tile replace	included with carpet	included with carpet	\$10,000 Every 20 years		10,000		
Clubhouse icemaker replace	combined above combined	\$5,000 every 5 yr combined	\$4,000 every 10 yr \$4,000 every		4,000		
Clubhouse oven replace	above	above	10 yr			4,000	
Clubhouse refrigerator/freezer	combined above	combined above	\$2,000 each every 10 yr			2,000	
	combined	combined	\$1,200 every				
Clubhouse washer/dryer	above combined	above combined	10 yr \$5,000 every 5				
Clubhouse copier replace	above	above	years	3,000			
Clubhouse Interior paint	not in engineer	\$20,000 every 5 yr	\$20,000 every 10 yr	0,000		20,000	
Clubhouse furniture		\$10.000 everv	\$45,000 every 15 yr, split into				
replacement	not in engineer	5 yr	3 \$10,000 every	11,677		5,000	
window coverings	not in engineer	not in study	10 years			10,000	
Clubhouse audi-visual	\$4,000 every 5	\$4,000 every 5	\$40,000 every				
equipment replace	yr	yr	10 yr	5,584			
Clubhouse staff computer equipment replace	\$4,000 every 7 yr	\$4,000 every 7 yr	\$5,000 every 5 yr				5,000
Clubhouse general use	J.	J.	\$3.500 every 5				5,000
computer equipment replace	not in engineer	not in study	yr \$40,000 every	3,237			
Clubhouse contingency	not in engineer	not in study	20 year			40,000	
Sales office renovations	not in engineer	\$10,000 in 2012 \$10,000 every	\$10,000 in 2012 \$10,000 every			10,000	
Roof ceiling joints	not in engineer	15 yr	15 yr				
Nature trail development and maintenance	not in engineer	\$10,000 every 5 yr	\$2,000 every 5 yr		2,000	8,000	
<b>R∂b£0cle</b> aning	not in engineer	\$5,000 every 8 yr	\$5,000 every 6 yr				

BellaVita at Green Tee							
2010 Scenario #24 Final Rese	rve						
Annual Expenses by Year, Cur							
· · · · · · · · · · · · · · · · · · ·							
Year				2010	2011	2012	2013
Year #	Engineers	2008 study	2010 study	1	2	3	4
Community bench	\$900 every 10	\$1,000 every	\$3,000 every				
replacement	yr, 9 at \$100	10 yr	10 yr			3,000	
Total				62,353	119,500	384,570	475,151
Adj for 3% inflation from 2009				62,353	126,778	420,230	534,786
					,	,	,
		contract	contract				
		amount by	amount by				
Plus painting per contract		section	home schedule	88,400	66,885	99,015	
Total expenses				150,753	193,663	519,245	534,786
Revenue per home, increase							
to 38.25 in 2011 and increase							
3%				35.54	39.50	40.69	41.91
Devenue					070.070		
Revenue				231,294	273,972	292,932	311,777
					070.010	1 070 000	
Beginning reserve balance				843,982	973,916	1,070,039	856,382
Plus fee revenue				231,294	273,972	292,932	311,777
Plus transfer from surplus				35,000 (150,753)	(402.002)	(540.045)	(504 700)
Less capital expenditure				(150,753)	(193,663)	(519,245)	(534,786)
Ending balance before interest				959,523	1 054 225	843,726	633,373
Int @ 1.5%				959,523 14,393	1,054,225 15,813	12,656	9,501
Ending balance				973,916	1,070,039	856,382	642,873
	<u> </u>			375,310	1,070,009	000,002	072,073
Reserve per home				1,795.79	1,851.28	1,427.30	1,036.89
				1,735.79	1,031.20	1,427.30	1,030.09
Assessment on 2008 study				35.54	36.60	37.70	38.83
				00.04	00.00	01.10	00.00
increase	1				2.90	2.99	3.08
	1						0.00
Increase due to fences					2.00		
increase due to other items					0.90		

BellaVita at Green Tee								
2010 Scenario #24 Final Resen Annual Expenses by Year, Curr								
Annual Expenses by Tear, Cull								
Year	2014	2015	2016	2017	2018	2019	2020	2021
Year #	5	6	7	8	9	10	11	12
# homes for expenses	620	620	620	620	620	620	620	620
# homes for painting based on :	60	50	48	21	131	111	49	69
Linear ft for common iron Linear ft for common wood								
Linear ft for unit iron Linear ft for unit wood	1212 4298	1433 2919	1102 4784	1433 5514	110 4784	1212 3163	551 3487	165 1825
	4290	2919	4704	5514	4704	5105	3407	1025
Site								
Retention Pond							4,000	
Sidewalk repair		5,000		5,000		5,000		5,000
Private street repair				50,000	50,000			
Concrete curb repairs		6,000			6,000			6,000
River pumps					8,000			
Entry gate paint								
Entry gates replace/modify								5,700
Entry gate motor replacement	6,500	3,250	3,250			6,500	3,250	3,250
Entry gate control computer replace	12,000					12,000		
Wrought iron paint common								
Wrought iron fencing replace common	-	-	-	-	-	-	-	-
Wood fence replace (common)	-	-	-	-	-	-	-	-
Lake Fountain repair								
Irrigation system repair	3,000			3,000			3,000	
Residential sprinkler controls replace \$100 home 1/20 of hଉମ୍ନଥେଶ 1	4,650	4,650	4,650	4,650	4,650	4,650	4,650	4,650

BellaVita at Green Tee								
2010 Scenario #24 Final Reservention Annual Expenses by Year, Curr								
Annual Expenses by rear, Cull								
Year	2014	2015	2016	2017	2018	2019	2020	2021
Year #	5	6	7	8	9	10	11	12
Monument & bell tower repair			5,000				5,000	
			0,000				0,000	
Contrete wall repair				5,000				
				5,000				
Clubhouse parking lights								
replace				6,000				
Clubhouse pavement repair				5,000				
Brick paver repairs				2,500				
Structure								
Exterior Systems Clubhouse, monument sign,								
tower & guardhouse painting						15,000		
						,		
Clubhouse roof replace								
Clubhouse gutters replace			4,000					
Residential door painting	33,067	33,067	33,067	33,067	33,067	33,067	33,067	33,067
	55,007	55,007	33,007	55,007	33,007	33,007	55,007	55,007
Residential house painting \$1500 per 5 years schedule								
homes	90,000	75,000	72,000	31,500	196,500	166,500	73,500	103,500
Unit iron fences replace	27,876	32,959	25,346	32,959	2,530	27,876	12,673	3,795
	,	. ,	_,	,	-,	,	-, 5	-,
Linit iron for				0 507				
Unit iron fences paint			-	9,587				-
Unit wood fences replace Mechanical Systems	73,066	49,623	81,328	93,738	81,328	53,771	59,279	31,025
wechanical Systems								
A in a secolition i								
Air conditioning systems replace	37,500							25,000
1/7/2011	57,500							20,000

BellaVita at Green Tee								
2010 Scenario #24 Final Reservent Annual Expenses by Year, Curr								
Year "	2014	2015	2016	2017	2018	2019	2020	2021
Year #	5	6	7	8	9	10	11	12
Electric water heater replace Miscellaneous Amenities								2,000
Exercise equipment replacement	2,500	2,500		2,500	2,500		2,500	2,500
Pool equipment-replace pumps	2,000	2,000	3,000	3,000	3,000	2,000	2,000	3,000
Pool equipment-replace filters								12,000
Pool equipment-replace water heaters			14,000					
Spa equipment-replace heater Swimming pool & spa re- plaster		3,500		3,500		3,500		3,500
pool deck								
Clubhouse carpet replace								10,000
Clubhouse tile replace								
Clubhouse icemaker replace								4,000
Clubhouse oven replace								
Clubhouse refrigerator/freezer						2,000		
Clubhouse washer/dryer						1,200		
Clubhouse copier replace		3,000					3,000	
Clubhouse Interior paint								
Clubhouse furniture replacement			15,000					15,000
window coverings								
Clubhouse audi-visual equipment replace						40,000		
Clubhouse staff computer					E 000	-,		
equipment replace Clubhouse general use					5,000			
computer equipment replace		3,500					3,500	
Clubhouse contingency								
Sales office renovations								
Roof ceiling joints Nature trail development and		10,000	2 000					0.000
	E 000		2,000				E 000	2,000
Røbato Røbaning	5,000						5,000	

BellaVita at Green Tee								
2010 Scenario #24 Final Reserv								
Annual Expenses by Year, Curr								
, unidal Expenses by Tear, ear								
Year	2014	2015	2016	2017	2018	2019	2020	2021
Year #	5	6	7	8	9	10	11	12
Community bench								
replacement								
Total	297,159	234,049	262,641	291,001	392,575	373,064	214,419	274,987
Adj for 3% inflation from 2009	344,488	279,466	323,015	368,631	512,221	501,366	296,806	392,065
Plus painting per contract								
Total expenses	344,488	279,466	323,015	368,631	512,221	501,366	296,806	392,065
	011,100	210,100	020,010		0.12,221	001,000	200,000	002,000
Revenue per home, increase								
to 38.25 in 2011 and increase								
3%	43.16	44.46	45.79	47.17	48.58	50.04	51.54	53.08
Davanua								
Revenue	321,131	330,765	340,687	350,908	361,435	372,278	383,447	394,950
Beginning reserve balance	642,873	628,808	690,308	718,600	711,391	569,014	446,525	541,164
Plus fee revenue	321,131	330,765	340,687	350,908	361,435	372,278	383,447	394,950
Plus transfer from surplus								
Less capital expenditure	(344,488)	(279,466)	(323,015)	(368,631)	(512,221)	(501,366)	(296,806)	(392,065)
Ending balance before interest	619,515	680,106	707,981	700,877	560,605	439,926	533,166	544,049
Int @ 1.5%	9,293	10,202	10,620	10,513	8,409	6,599	7,997	8,161
Ending balance	628,808	690,308	718,600	711,391	569,014	446,525	541,164	552,209
Reserve per home	1,014.21	1,113.40	1,159.03	1,147.40	917.76	720.20	872.84	890.66
	1,011.21	.,110.10	1,100.00	1,11110	0.1.10	, 20.20	0.2.04	000.00
Assessment on 2008 study	39.99	41.19	42.43	43.70	45.01	46.37	47.76	49.19
increase	3.17	3.26	3.36	3.46	3.57	3.67	3.78	3.90
Increase due to fences								
increase due to other items								

BellaVita at Green Tee								
2010 Scenario #24 Final Resen Annual Expenses by Year, Curr								
Year Year #	2022 13	2023 14	2024 15	2025 16	2026 17	2027 18	2028 19	2029 20
# homes for expenses # homes for painting based on s	620 81	620 60	620 50	620 48	620 21	620 131	620 111	620 49
	01	00	50	40	21	131		45
Linear ft for common iron							240	
Linear ft for common wood Linear ft for unit iron	496						240	
Linear ft for unit wood	2960	3325					6163	4298
Site								
Retention Pond								
Sidewalk repair		5,000		5,000		5,000		5,000
Private street repair	50,000	50,000				50,000	50,000	
Concrete curb repairs			6,000			6,000		
			-,			_ ,		
River pumps					8,000			
Entry gate paint								
Entry gates replace/modify								5700
Entry gate motor replacement			6,500	3,250	3,250			6,500
Entry gate motor replacement			0,000	3,230	3,230			0,000
Entry gate control computer								
replace			12,000					12,000
Wrought iron paint common								
wrodgin non paint common								
Wrought iron fencing replace								
common	-	-	-	-	-	-	-	-
Wood fence replace								
(common)	-	-	-	-	-	-	4,080	-
Lake Fountain repair	20,000	20,000						
		0.000			0.000			2 000
imgation system repair		3,000			3,000			3,000
Residential sprinkler controls								
	4 650	4 650	4 650	4 650	4 650	4 650	4 650	4,650
Irrigation system repair Residential sprinkler controls replace \$100 home 1/20 of tromaged 1	4,650	3,000	4,650	4,650	3,000	4,650	4,650	

BellaVita at Green Tee								
2010 Scenario #24 Final Reserv								
Annual Expenses by Year, Curr								
Year	2022	2023	2024	2025	2026	2027	2028	2029
Year #	13	14	15	16	17	18	19	20
Monument & bell tower repair			5,000				5000	
			0,000				0000	
Contrete wall repair	5,000					5,000		
Clubhouse parking lights								
replace	6,000					6,000		
Clubhouse pavement repair	5,000					5,000		
	0 - 00					0 - 00		
Brick paver repairs Structure	2,500					2,500		
Exterior Systems								
Clubhouse, monument sign, tower & guardhouse painting								15,000
tower & guardhouse painting								13,000
Clubhouse roof replace								
Clubhouse gutters replace								
Clubilouse guilers replace								
Desidential deservations	00.007	00.007	00.007	00.007	00.007	00.007	00.007	00.007
Residential door painting	33,067	33,067	33,067	33,067	33,067	33,067	33,067	33,067
Residential house painting								
\$1500 per 5 years schedule homes	121,500	90,000	75,000	72,000	31,500	196,500	166,500	73,500
	121,000	30,000	10,000	12,000	01,000	100,000	100,000	10,000
Unit iron fences replace	11,408	-	-	-	-	-	-	-
Unit iron fences paint	4,794							
	.,							
Unit wood fences replace	50,320	56,525	-	-	-	-	104,771	73,066
Mechanical Systems								
Air conditioning systems replace	50,000	50,000	37,500					
1/7/2011	00,000	00,000	01,000					

BellaVita at Green Tee 2010 Scenario #24 Final Reserv								
Annual Expenses by Year, Curr								
Year	2022	2023	2024	2025	2026	2027	2028	2029
Year #	13	14	15	16	17	18	19	2023
Electric water heater replace								
Miscellaneous Amenities								
Exercise equipment								
replacement		2,500	2,500		2,500	2,500		2,500
Pool equipment-replace								
pumps	3,000	3,000	2,000	2,000	3,000	3,000	3,000	2,000
Pool equipment-replace filters								
Pool equipment-replace water								
heaters			14,000					
Spa equipment-replace heater		3,500		3,500		3,500		3500
Swimming pool & spa re- plaster	40,000					,		
pool deck	20,000							
Clubhouse carpet replace	10,000							
Clubhouse tile replace								
Clubhouse icemaker replace								
Clubhouse oven replace	4,000							
Clubhouse refrigerator/freezer	2,000							2000
Clubhouse washer/dryer								1200
				0.000				
Clubhouse copier replace				3,000				
Clubhouse Interior paint	20,000							
Clubhouse furniture replacement					15,000			
					13,000			
window coverings Clubhouse audi-visual	10,000							
equipment replace Clubhouse staff computer								40,000
equipment replace		5,000					5,000	
Clubhouse general use computer equipment replace				3,500				
Clubhouse contingency				0,000				
Sales office renovations								
Roof ceiling joints Nature trail development and								
maintenance					2,000			
RøØedeaning					5,000			

BellaVita at Green Tee								
2010 Scenario #24 Final Reserv								
Annual Expenses by Year, Curr								
Year	2022	2023	2024	2025	2026	2027	2028	2029
Year #	13	14	15	16	17	18	19	20
Community bench								
replacement	3,000							
Total	476,238	326,242	198,217	129,967	110,967	322,717	376,068	282,683
Adj for 3% inflation from 2009	699,372	493,470	308,815	208,558	183,411	549,404	659,437	510,556
Plus painting per contract								
Total expenses	699,372	493,470	308,815	208,558	183,411	549,404	659,437	510,556
Revenue per home, increase								
to 38.25 in 2011 and increase								
3%	54.68	56.32	58.01	59.75	61.54	63.39	65.29	67.25
Revenue	406,799	419,003	431,573	444,520	457,855	471,591	485,739	500,311
				,•=•	,			
Beginning reserve balance	552,209	263,531	191,899	319,377	563,668	850,685	784,465	619,929
Plus fee revenue	406,799	419,003	431,573	444,520	457,855	471,591	485,739	500,311
Plus transfer from surplus	,	,		,	,	,	,	
Less capital expenditure	(699,372)	(493,470)	(308,815)	(208,558)	(183,411)	(549,404)	(659,437)	(510,556)
Ending balance before interest	259,636	189,063	314,657	555,338	838,113	772,872	610,767	609,683
Int @ 1.5%	3,895	2,836	4,720	8,330	12,572	11.593	9,162	9,145
Ending balance	263,531	191,899	319,377	563,668	850,685	784,465	619,929	618,829
Reserve per home	425.05	309.52	515.12	909.14	1,372.07	1,265.27	999.89	998.11
Assessment on 2008 study	50.66	52.18	53.75	55.36	57.02	58.73	60.50	62.31
increase	4.01	4.13	4.26	4.38	4.52	4.65	4.79	4.94
Increase due to fences								
increase due to other items								

BellaVita at Green Tee						
2010 Scenario #24 Final Reserv						
Annual Expenses by Year, Curr						
Year Year #	2030 21	total	home	common	club	
# homes for expenses	620					
# homes for painting based on s	69	1515				
Linear ft for common iron						
Linear ft for common wood						
Linear ft for unit iron						
Linear ft for unit wood	2919					
Site						
Retention Pond		4,000		4,000		
Sidewalk repair		55,000		55,000		
Private street repair		400,000		400,000		
Concrete curb repairs	6,000	42,000		42,000		
River pumps		16,000		16,000		
Entry gate paint				-		
Entry gates replace/modify		17,100		17,100		
Entry gate motor replacement	3,250	52,000		52,000		
Entry gate control computer replace		48,000		48,000		
Wrought iron paint common		1,896		1,896		
Wrought iron fencing replace common	_	21,804		21,804		
Wood fence replace						
(common)	-	8,160		8,160		
Lake Fountain repair		80,000		80,000		
Irrigation system repair		21,000		21,000		
Residential sprinkler controls replace \$100 home 1/20 of hଫାଉଇସ 1	4,650	91,200	91,200			

BellaVita at Green Tee						
2010 Scenario #24 Final Reserv						
Annual Expenses by Year, Curr						
Year	2030	total	homo	0000000	alub	
Year #	21	total	home	common	club	
Monument & bell tower repair		25,000		25,000		
Contrete wall repair		20,000		20,000		
Clubhouse parking lights replace		24,000		24,000		
Clubhouse pavement repair		20,000		20,000		
Brick paver repairs Structure Exterior Systems		10,000 		10,000		
Clubhouse, monument sign,				00.000		
tower & guardhouse painting		30,000		30,000		
Clubhouse roof replace		_			_	
Clubhouse gutters replace		4,000			4,000	
Residential door painting	33,067	653,450	653,450			
Residential house painting \$1500 per 5 years schedule homes	103,500	1,860,000	1,860,000			
Unit iron fences replace	-	220,501	220,501			
Unit iron fences paint		33,555	33,555			
Unit wood fences replace Mechanical Systems	49,623	962,234	962,234			
Air conditioning systems replace 1/7/2011		325,000			325,000	

BellaVita at Green Tee						
2010 Scenario #24 Final Reserv						
Annual Expenses by Year, Curr						
Year	2030					
Year #	2030	total	home	common	club	
Electric water heater replace		4,000			4,000	
Miscellaneous Amenities		-				
Eversion equipment						
Exercise equipment replacement	2,500	35,000			35,000	
1	,				,	
Pool equipment-replace						
pumps	2,000	52,000			52,000	
Pool equipment-replace filters		24,000			24,000	
Pool equipment-replace water						
heaters		28,000			28,000	
Spa equipment-replace heater Swimming pool & spa re-		35,000			35,000	
plaster		80,000			80,000	
pool deck		40,000			40.000	
		40,000			40,000	
Clubhouse carpet replace		40,000			40,000	
		40,000			40,000	
Clubbauga tila raplaga		10.000			10.000	
Clubhouse tile replace		10,000			10,000	
Clubhouse icemaker replace		8,000			8,000	
Clubhouse oven replace		8,000			8,000	
Clubhouse refrigerator/freezer		8,000			8,000	
Clubhouse washer/dryer		2,400			2,400	
	0000	40.000			40.000	
Clubhouse copier replace	3000	12,000			12,000	
Clubhouse Interior paint		40,000			40,000	
Clubhouse furniture						
replacement		50,000			50,000	
window opyoringo		20,000			20,000	
window coverings Clubhouse audi-visual		20,000			20,000	
equipment replace		80,000			80,000	
Clubhouse staff computer equipment replace		20,000			20,000	
Clubhouse general use						
computer equipment replace	3500	14,000			14,000	
Clubhouse contingency		40,000			40,000	
Sales office renovations		10,000			10,000	
Roof ceiling joints	10000	20,000			20,000	
Nature trail development and maintenance		16,000		16,000		
				10,000		
Røb20cleaning		15,000			15,000	

BellaVita at Green Tee						
2010 Scenario #24 Final Reserv						
Annual Expenses by Year, Curr						
Annual Expenses by Teal, Cult						
Year	2030					
Year #	21	total	home	common	club	
Community bench						
replacement		6,000		6,000		
Total	221,090	5,763,300				
=		5,763,300	3,820,940	917,960	1,024,400	5,763,300
Adj for 3% inflation from 2009	411,292					
Plus painting per contract		165,900	165,900			165,900
Total expenses	411,292	5,929,200	3,986,840	917,960	1,024,400	5,929,200
			0.07	0.15	0.47	
Bouopuo por homo, ingragoo			0.67	0.15	0.17	
Revenue per home, increase to 38.25 in 2011 and increase						
3%	69.26					
576	09.20					
Revenue	515,320					
	010,020					
Beginning reserve balance	618,829					
Plus fee revenue	515,320					
Plus transfer from surplus	0.0,020					
Less capital expenditure	(411,292)					
Ending balance before interest	722,857					
Int @ 1.5%	10,843					
Ending balance	733,700					
Reserve per home	1,183.39					
Assessment on 2008 study	64.18					
increase	5.08					
Increase due to fences						
increase due to other items						
				1		